# MASPS for ADS-B

Tracking Information (committee secretary only)		
Change Issue Number	11	
Submission Date	1/11/01	
Status (open/closed/deferred)	CLOSED	
Last Action Date	5/24/01	

Short Title for Change Issue:	Requests for clarification on "TCP types" and the use of the "TCP Data Valid" subfield.
-------------------------------	---

MASPS Document Reference:		Originator Information:		
Entire document (y/n)		Name	Bob Hilb / UPS	
Section number(s)	2.1.2.3.2.1	Phone	(502) 359-7396	
Paragraph number(s)		E-mail	Bob.hilb@air.ups.com	
Table/Figure number(s)	Tables 3-6 and 3-7	Other		

Pro	Proposed Rationale for Consideration (originator should check all that apply):				
	Item needed to support of near-term MASPS/MOPS development				
X	DO-260/ED-102 1090 MHz Link MOPS Rev A				
	ASA MASPS				
	TIS-B MASPS				
	UAT MOPS				
	Item needed to support applications that have well defined concept of operation				
	Has complete application description				
	Has initial validation via operational test/evaluation				
	Has supporting analysis, if candidate stressing application				
	Item needed for harmonization with international requirements				
	Item identified during recent ADS-B development activities and operational evaluations				
	MASPS clarifications and correction item				
	Validation/modification of questioned MASPS requirement item				
	Military use provision item				
X	New requirement item (must be associated with traffic surveillance to support ASAS)				

Nature of Issue:		Editorial		Clarity		Performance	X	Functional
Issue Description: The att	<u>Issue Description</u> : The attached comments <b>requesting clarification of the various TCP types</b> ( <b>TCP Leg</b>							
types) and a note be added	to th	e 1090 MOP	S to	help better e	xplai	n the use of the '	<b>TCI</b>	P Data Valid" Subfield
were presented to the SC-1	86 p	lenary in refe	erenc	e to the ballo	ot on	the 1090 MHz A	DS-	B MOPS (DO-260). It
was agreed that these issue	s wo	uld be defer	red f	rom conside	ratio	n in DO-260 unt	il fir	st considered for
inclusion in a future revision	on of	the ADS-B	MAS	SPS. Include	d wi	th the attached co	omm	ents are the official
responses from working gr	oup 3	3, which was	cha	rted with dev	elop	ment of DO-260		

<u>Originator's proposed resolution if any</u>: Proposed resolution is attached with comment from DO-260 ballot. A specific MASPS change proposal related to this topic is found on attachment #2 which was submitted by Capt. Hilb in November, 2000.

#### Working Group 6 Deliberations:

<u>February 13, 2001</u>: Chris Moody's comment from the DO-260 ballot was added to this Issue Paper as a result of the ad hoc groups deliberations at their January, 2001 meeting. This comment was previously not included in any Issue Papers.

(continued on next page)

#### Working Group 6 Deliberations (continued):

May 24, 2001: This Issue Paper was discussed by the ad hoc group at their May 2001 meeting. It was agreed to <u>CLOSE this Issue Paper</u> and integrate Capt. Hilb's specific proposal documented in attachment #2 into Issue Paper 21, "TCP Types and Parameters".

Issue # 11 Page 2

# ADS-B 1090 MHz Rev A Comments Related to MASPS Changes RTCA SC-186 WG-3/EUROCAE WG-51 SG-1

#	Comment Author	DO-260 Section	Page	Comment / Rationale	Suggested Resolution
14	C.Moody (7)	2.2.3.2.7.1.3	91	Are all these various trajectory types required by the MASPS? Doesn't the MASPS assume a straight geodesic course to all TCPs?	Include a NOTE that explains why this capability beyond the MASPS is included.
				<b>WG#3 Position:</b> Non-issue. WG#3 admittedly went beyond the MASPS requirements.	
15	Hilb (5)	2.2.3.2.7.1.4	92	The use of TCP Data Valid Subfield is not well explained.	Add Note: The TCP Valid Subfield is used to indicate that the aircraft is
				<b>Temporary resolution:</b> Changed 2.2.3.2.7.1.4 to show zero (0) as the only acceptable coding value for initial 1090 MOPS publication. Changed 2.4.3.2.7.1.4, Step 1 to test for condition zero (0) only.	flying to the broadcast TCP and will arrive at the time projected. This indication is intended primarily for new aircraft and manufacturers will design automation systems to insure
				<b>WG#3 Position:</b> WG#3 agrees this issue needs addressed in DO-242A.	a TBD level of compliance to a TCP before indicating the information is valid.

#### **Proposed MASPS Changes**

#### 2.1.2.3.2.1 Current Trajectory Change Point

The TCP from the transmitting aircraft is the point in three-dimensional space where the current operational trajectory is planned to change, and estimated remaining flight time to that point. A TCP transmission indicates that the aircraft intends to fly directly, via a great circle route, to that point. The TCP is defined as a five-element vector consisting of the following:

- Latitude (WGS-84)
- Longitude (WGS-84)
- Altitude (pressure altitude or flight level )
- Time to go (TTG) to the indicated point in space
- Validity bit

Note: The Validity bit is used to indicate that the aircraft is flying to the broadcast TCP and will arrive at the time projected. This indication is intended primarily for new aircraft and manufacturers will design automation systems to insure a TBD level of compliance to a TCP before broadcasting this bit.

The TCP required received...

#### 3.4.4 Minimum ADS-B Report Requirements for Equipage Classes

**Table 3-6 Mode-status Report Definition** 

Element #	Contents						
1	Participant Address (Section 2.1.2.1.2)						
2	2 Call Sign (Up to 8 Alpha-numeric Characters) (Section 2.1.2.1.1)						
3	Participant Category (Section 2.1.2.1.3)						
4	Surveillance Support Code(Normal/Default) (note 3)						
5	Emergency/Priority Status (Section 2.1.2.3.1)						
6	Class Codes (Section 2.1.2.4)						
7	7 TCP Latitude (Section 2.1.2.3.2)						
8	8 TCP Longitude (Section 2.1.2.3.2)						
9	9 TCP Altitude (Baro Alt/FL) (Section 2.1.2.3.2)						
<u>10</u>	10 TCP Validity(Section 2.1.2.3.2)						
<del>10</del> 11	TTG (Section 2.1.2.3.2)						
<del>11</del> 12	4412 Operational Mode Specific Data						
<del>12</del> 13	Flight Mode Specific Data (note 4)						
<del>13</del> <u>14</u>	Time of Applicability (Section 2.1.1.4)						
<u>15</u>	ACAS/TCAS Capability Code (Section 2.1.2.5)						

## **Proposed MASPS Changes**

## <u>Table 3-7</u> TCP+1 On-Condition Report Definition

Element #	Element # Contents					
1	Participant Address (Section 2.1.2.1.2)					
2	2 TCP+1 (Lat.) (Section 2.1.2.3.2)					
3	3 TCP+1(Long.) (Section 2.1.2.3.2)					
4	TCP+1 Altitude (Baro/FL) (Section 2.1.2.3.2)					
5	TCP+1 TTG (Section 2.1.2.3.2)					
<u>6</u>	TCP Validity(Section 2.1.2.3.2)					
<u>67</u>	Time of Applicability (Section 2.1.1.4)					